

(c) Advise Columbia Tower by radio or telephone when MU Values rise above 40 in all zones of the runway previously reporting values less than 40.



Philip L. Fuller
Air Traffic Manager
Columbia Air Traffic Control Tower



Mike Flack
Executive Director
Columbia Metropolitan Airport




EXHIBIT 7: LETTERS OF AGREEMENT